	l	JST Service Provider List (Mo	untains)		
Company		Listing Submitted		Area of state conducts work	
Advanced Environmental Services, Inc.		Phone (336) 282-3586		Coastal (East of I-95): Yes	
PO Box 38218		Fax (336) 282-3587		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27438	10.	ebsite advancedenvironmental.com		Mountains (West of I-77): Yes	
	oliance Test	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No	*	
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	2/1/2021	Area of state conducts work	
Advanced Environmental Solutions, LLC		Phone (828) 664-9822		Coastal (East of I-95): Yes	
P.O. Box 1426		Fax (866) 425-2661		Central (West of I-95 and East of I-77): Yes	
Black Mountain, NC 28711		144 (000) 420 2001			
	W	ebsite advancedenvironmentalsolutions.com		Mountains (West of I-77): Yes	
Comp	oliance Test	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Environmental Engineer/Geologist Soil and GW Cleanu Oil and Solvent Recycling:	No No	Waste Disposal and Treatment: Other:	No		
			No		

		UST Service Provider List (Moเ	untains)		
Company		Listing Submitted	5/17/2021	Area of state conducts work	
AES of Greenville LLC		Phone (252) 758-3311		Coastal (East of I-95): Yes	
141 S. Market Street		Fax (252) 481-5814		Central (West of I-95 and East of I-77): Yes	
Washington, NC 27889				Mountains (West of I-77): Yes	
	V	Website www.aes-nc.com			
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironment	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	l No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	4/15/2021	Area of state conducts work	
American UST Compliance Testing		Phone (919) 777-8543		Coastal (East of I-95): Yes	
180 BPW Club Rd. A-1		Fax		Central (West of I-95 and East of I-77): Yes	
Carrboro, NC 27510					
				Mountaine (West of L-77): Ves	
	V	Website		Mountains (West of I-77): Yes	
Comp		Website sting and Monitoring		Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Comp Automatic Line Leak Detector Testing:			Yes	. , ,	Yes
	pliance Tes	eting and Monitoring	Yes No	UST Equipmment Service Contractors	<u>Yes</u> No
Automatic Line Leak Detector Testing:	pliance Tes <u>Yes</u>	oting and Monitoring Overfill Prevention Equipment Operability Check:		UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Tes Yes Yes No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No <u>Yes</u>	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No <u>Yes</u>
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No <u>Yes</u> <u>Yes</u>	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No Yes No Yes No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Yes Yes No No Yes Yes Yes No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No <u>Yes</u> <u>Yes</u> No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No Yes No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No Yes Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes No Yes Yes No Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No Yes No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes No Yes Yes No Yes Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No <u>Yes</u> <u>Yes</u> No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No No Yes Yes No Yes Yes No Yes No Yes No Yes No Yes No No Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No Yes Yes No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En	Yes Yes No No Yes Yes No Yes Yes No Yes No Yes No Yes No Yes No No Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	No Yes Yes No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No No Yes Yes No Yes Yes No Yes No Yes No Yes No Yes No No Yes	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No Yes Yes No No Yes No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No No

	l	JST Service Provider List (Mou	ıntains)		
Company		Listing Submitted		Area of state conducts work	
Apex Engineering, PC		Phone (301) 417-0200		Coastal (East of I-95): Yes	
15850 Crabbs Branch Way		Fax (301) 975-0169		Central (West of I-95 and East of I-77): Yes	
Suite 200 Rockville, Maryland 20855-				Mountains (West of I-77): Yes	
Trockvine, Marylana 20000	VV	ebsite <u>www.apexcos.com</u>		,	
Comp	pliance Testi	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Ei	nvironmenta	Il Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	Yes				
Company		Listing Submitted	7/19/2022	Area of state conducts work	
Company B & M WEST CONSTRUCTION CO OF TEXAS I	DBA D.		7/19/2022		
• •	DBA D.	Phone (863) 519-4441	7/19/2022	Coastal (East of I-95): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS I	DBA D.		7/19/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD		Phone (863) 519-4441	7/19/2022	Coastal (East of I-95): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860	W	Phone (863) 519-4441 Fax (863) 519-4407	7/19/2022	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860	W	Phone (863) 519-4441 Fax (863) 519-4407 Phone (863) 519-4407 Phone (863) 519-4401	7/19/2022 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860	W pliance Testi	Phone (863) 519-4441 Fax (863) 519-4407 Pebsite DWSHOUPPE.COM Ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp	W pliance Testi No	Phone (863) 519-4441 Fax (863) 519-4407 Pebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	W pliance Testi No No	Phone (863) 519-4441 Fax (863) 519-4407 Lebsite DWSHOUPPE.COM Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	W pliance Testi No No No	Phone (863) 519-4441 Fax (863) 519-4407 Lebsite DWSHOUPPE.COM Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No <u>Yes</u>
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	W pliance Testi No No No No	Phone (863) 519-4441 Fax (863) 519-4407 Pebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No <u>Yes</u> No
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Windows Testi No No No No No No	Phone (863) 519-4441 Fax (863) 519-4407 Pebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No <u>Yes</u> No No
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Windows Testi No No No No No No	Phone (863) 519-4441 Fax (863) 519-4407 Pebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No Yes No No No
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Wipliance Testi No No No No No No No No	Phone (863) 519-4441 Fax (863) 519-4407 Pebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Wipliance Testi No No No No No No No No	Phone (863) 519-4441 Fax (863) 519-4407 Pebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Wind pliance Testing No	Phone (863) 519-4441 Fax (863) 519-4407 Pebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	Windows Policy P	Phone (863) 519-4441 Fax (863) 519-4407 Lebsite DWSHOUPPE.COM Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS I 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Windows Policy P	Phone (863) 519-4441 Fax (863) 519-4407 Pebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes
B & M WEST CONSTRUCTION CO OF TEXAS II 209 E BADCOCK BLVD MULBERRY, FL 33860 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	Webliance Testi No	Phone (863) 519-4441 Fax (863) 519-4407 Pebsite DWSHOUPPE.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No No No Yes

		UST Service Provider List (Mou	ıntains)		
Company		Listing Submitted	7/30/2020	Area of state conducts work	
Blue Ridge Geological Services, Inc.		Phone (336) 382-6849		Coastal (East of I-95): Yes	
7356 Belmont Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Trinity, NC 27370				Mountains (West of I-77): Yes	
	V	Website www.blueridgegeo.com			
Comp	liance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
En	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	2/1/2021	Area of state conducts work	
Company Buckeye Elm Contracting		Listing Submitted Phone (888) 315-8663	2/1/2021	Area of state conducts work Coastal (East of I-95): Yes	
Buckeye Elm Contracting PO Box 1026			2/1/2021	Coastal (East of I-95): Yes	
Buckeye Elm Contracting		Phone (888) 315-8663 Fax	2/1/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Buckeye Elm Contracting PO Box 1026	V	Phone (888) 315-8663	2/1/2021	Coastal (East of I-95): Yes	
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028		Phone (888) 315-8663 Fax	2/1/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028		Phone (888) 315-8663 Fax Website www.buckeye-elm.com	2/1/2021 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comp	oliance Tes	Phone (888) 315-8663 Fax Website www.buckeye-elm.com ting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comp Automatic Line Leak Detector Testing:	oliance Tes No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com ting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com Iting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com Iting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com Iting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (888) 315-8663 Fax Website www.buckeye-elm.com Iting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No N	Phone (888) 315-8663 Fax Nebsite www.buckeye-elm.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (888) 315-8663 Fax Website www.buckeye-elm.com Iting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Mor	untains)		
Company		Listing Submitted	1/10/2022	Area of state conducts work	
Bunnell-Lammons Engineering, Inc.		Phone (828) 277-0100		Coastal (East of I-95): Yes	3
130 Oval Road		Fax (828) 277-0110		Central (West of I-95 and East of I-77): Yes	3
Arden, NC 28704				Mountains (West of I-77): Yes	3
	,	Website <u>www.blecorp.com</u>			
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Eı	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other: Trust Fund	Projects		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/18/2020	Area of state conducts work	
Company Cathodic Protection Services, Inc.		Phone (423) 895-1500	8/18/2020	Area of state conducts work Coastal (East of I-95): Yes	3
Cathodic Protection Services, Inc. 445 Gap Creek Rd.		Phone (423) 895-1500	8/18/2020	Coastal (East of I-95): Yes	
Cathodic Protection Services, Inc.		Phone (423) 895-1500 Fax (423) 542-8955	8/18/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	3
Cathodic Protection Services, Inc. 445 Gap Creek Rd.	,	Phone (423) 895-1500	8/18/2020	Coastal (East of I-95): Yes	3
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643		Phone (423) 895-1500 Fax (423) 542-8955	8/18/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	3
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643		Phone (423) 895-1500 Fax (423) 542-8955 Website	8/18/2020 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	3
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643	oliance Tes	Phone (423) 895-1500 Fax (423) 542-8955 Website sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	5
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643 Company Automatic Line Leak Detector Testing:	oliance Tes	Phone (423) 895-1500 Fax (423) 542-8955 Website Sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (423) 895-1500 Fax (423) 542-8955 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No Yes Yes Yes Yes	Phone (423) 895-1500 Fax (423) 542-8955 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No Yes Yes Yes No	Phone (423) 895-1500 Fax (423) 542-8955 Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No No
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No Yes Yes Yes No No	Phone (423) 895-1500 Fax (423) 542-8955 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No No
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No Yes Yes Yes No	Phone (423) 895-1500 Fax (423) 542-8955 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No Yes Yes Yes No No No	Phone (423) 895-1500 Fax (423) 542-8955 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No No
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No Yes Yes Yes No No No	Phone (423) 895-1500 Fax (423) 542-8955 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No Yes Yes Yes No	Phone (423) 895-1500 Fax (423) 542-8955 Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	No No No Yes Yes Yes No	Phone (423) 895-1500 Fax (423) 542-8955 Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No Yes Yes Yes No	Phone (423) 895-1500 Fax (423) 542-8955 Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No No

	Į	JST Service Provider List (Mou	ıntains)		
Company		Listing Submitted	8/18/2020	Area of state conducts work	
Charles Broadfoot & Associates, Inc.		Phone (910) 574-4748		Coastal (East of I-95): Yes	
PO Box 53730		Fax 253-681-05		Central (West of I-95 and East of I-77): Yes	
1827 Morganton Rd. Fayetteville, NC 28305		to the state of th		Mountains (West of I-77): Yes	
Tayonovino, NO 2000	V\	/ebsite <u>www.ustcomonline.com</u>			
Comp	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Off	Overfill Prevention Equipment Operability Check:	Off	Dispenser Meter Repair/Calibration:	Off
Containment Sump Testing:	Off	Statistical Iventory Reconciliation Services:	Off	Leak Detection Equipment Installation Servicing:	Off
Corrosion Protection Design Experts:	Off	Spill Prevention Equipment Testing:	Off	Spill Bucket Installation Repair:	Off
Corrosion Protection System Repairs:	Off	Tank Tightness Testing:	Off	UST Equipment Installation - Other:	Off
Corrosion Protection System Testing:	Off	UST Internal Inspections (Integrity Assessments):	Off	UST Equipment Repair:	Off
Leak Detection Equipment Operability Check:	Off	UST Internal Lining Inspections:	Off	UST System Installation - Complete Systems:	Off
Leak Detection Monitoring Services:	Off	Other:		UST Piping/Sump Installation:	Off
Line Tightness Testing:	Off			UST System Removal:	Off
E	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Off	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Off	UST Equipment Verification:	Off		
Environmental Engineer/Geologist Soil and GW Cleanu	ı Off	Waste Disposal and Treatment:	Off		
Oil and Solvent Recycling:	Off	Other:			
Soil and Water Testing Lab:	Off				
Company		Listing Submitted	5/26/2021	Area of state conducts work	
Company Christopher Dunlap, P.G.		Phone (828) 505-6301	5/26/2021	Area of state conducts work Coastal (East of I-95): No	
Christopher Dunlap, P.G. 166 Michigan Avenue		Phone (828) 505-6301	5/26/2021	Coastal (East of I-95): No	
Christopher Dunlap, P.G.			5/26/2021	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
Christopher Dunlap, P.G. 166 Michigan Avenue	W	Phone (828) 505-6301	5/26/2021	Coastal (East of I-95): No	
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806		Phone (828) 505-6301 Fax	5/26/2021	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806		Phone (828) 505-6301 Fax /ebsite	5/26/2021 No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806	pliance Test	Phone (828) 505-6301 Fax /ebsite ing and Monitoring		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806 Comparison Line Leak Detector Testing:	pliance Test No	Phone (828) 505-6301 Fax /ebsite ting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Test No No	Phone (828) 505-6301 Fax /ebsite ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806 Comparison Comparison Comparison Comparison Comparison Protection Design Experts:	pliance Test No No No	Phone (828) 505-6301 Fax /ebsite ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (828) 505-6301 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (828) 505-6301 Fax /ebsite ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (828) 505-6301 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (828) 505-6301 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (828) 505-6301 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (828) 505-6301 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	No N	Phone (828) 505-6301 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (828) 505-6301 Fax /ebsite ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Mou	untains)		
Company		Listing Submitted	6/17/2020	Area of state conducts work	
Clark Group dba Clark Environmental Services	s, PC	Phone (910) 392-5555		Coastal (East of I-95): Yes	
P.O. Box 10136		Fax (910) 392-5552		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28404		. ,		Mountains (West of I-77): Yes	
	V	Vebsite www.clarkgroup.us		meanane (rest et 177). Tes	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/14/2021	Area of state conducts work	
Cobb Environmental & Technical Services, Inc).	Phone (662) 841-0995		Coastal (East of I-95): Yes	
P. O. Box 1602, Tupelo, MS 38802		Fax (662) 841-0810		Central (West of I-95 and East of I-77): Yes	
871 South Green Street		1 dx (002) 041-0010			
Tupelo, MS 38804	V	Website www.cobbenv.com		Mountains (West of I-77): Yes	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
10 % 11M (T () 1 1					
Soil and Water Testing Lab:	No				

		UST Service Prov	vider List (Mou	ntains)		
Company			Listing Submitted	12/30/2021	Area of state conducts work	
Crompco, LLC		Phone (610) 278-7203			Coastal (East of I-95): Yes	
1815 Gallagher Road		Fax (610) 278-7621			Central (West of I-95 and East of I-77): Yes	
Plymouth Meeting, PA 19462					Mountains (West of I-77): Yes	
		Website www.crompco.com	<u>n</u>		,	
Comp	oliance Te	esting and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment	t Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconcilia	tion Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment To	esting:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Inte	egrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspection	ns:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironme	ntal Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants	:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatme	nt:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	9/28/2022	Area of state conducts work	
D. H. Griffin Wrecking Company		Phone (336) 214-9012			Coastal (East of I-95): Yes	
4716 Hilltop Road		Fax			Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27407					Mountains (West of I-77): Yes	
		Website www.dhgriffin.com	1		moditalits (west of 1-17).	
Comp	oliance Te	esting and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment	t Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconcilia	tion Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment To	esting:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Inte	egrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspection	ns:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironme	ntal Service Firms			Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants	:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatme	nt:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:	Vacuum Truck S	ervices		
Soil and Water Testing Lab:	No					

: Yes
: Yes
: Yes
ctors
No
g: No
No
No
No
No
No
No
Yes
: Yes
1/
: Yes
: Yes
ctors
ctors Yes
ctors Yes Yes
Yes Yes Yes Yes
Yes Yes Yes Yes Yes
Yes Yes Yes Yes Yes Yes Yes
Yes
Yes
Yes
Yes
Yes
Yes

		UST Service Provider List (Mou	ıntains)		
Company		Listing Submitted	1/4/2022	Area of state conducts work	
EnviroTrac Ltd.		Phone (336) 763-6025		Coastal (East of I-95): Yes	
7343 West Friendly Avenue		Fax		Central (West of I-95 and East of I-77): Yes	
Suite J Greensboro, NC 27410				Mountains (West of I-77): Yes	
Gleensboid, NC 27410		Website envirotrac.com		, 11	
Comp	liance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	7/30/2020	Area of state conducts work	
Envirovation Geologic Consulting and Mappin	g, PC	Phone (828) 407-0613		Coastal (East of I-95): No	
Envirovation Geologic Consulting and Mappin 719-A Greenway Rd	g, PC	·			
719-A Greenway Rd PO Box 3425	g, PC	Phone (828) 407-0613 Fax		Central (West of I-95 and East of I-77): Yes	
719-A Greenway Rd	g, PC	·			
719-A Greenway Rd PO Box 3425 Boone, NC 28607		Fax		Central (West of I-95 and East of I-77): Yes	
719-A Greenway Rd PO Box 3425 Boone, NC 28607		Fax Website https://envirovationconsulting.com/	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
719-A Greenway Rd PO Box 3425 Boone, NC 28607	oliance Te	Fax Website https://envirovationconsulting.com/ esting and Monitoring	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
719-A Greenway Rd PO Box 3425 Boone, NC 28607 Comp Automatic Line Leak Detector Testing:	oliance Te	Fax Website https://envirovationconsulting.com/ esting and Monitoring Overfill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
719-A Greenway Rd PO Box 3425 Boone, NC 28607 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	oliance Te No No	Website https://envirovationconsulting.com/ esting and Monitoring https://envirovationconsulting.com/ esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
719-A Greenway Rd PO Box 3425 Boone, NC 28607 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No	Fax Website https://envirovationconsulting.com/ Pesting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
719-A Greenway Rd PO Box 3425 Boone, NC 28607 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Website https://envirovationconsulting.com/ https://enviro	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No No
719-A Greenway Rd PO Box 3425 Boone, NC 28607 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No	Fax Website https://envirovationconsulting.com/ esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
719-A Greenway Rd PO Box 3425 Boone, NC 28607 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Website https://envirovationconsulting.com/ https://enviro	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
719-A Greenway Rd PO Box 3425 Boone, NC 28607 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Website https://envirovationconsulting.com/ https://enviro	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
719-A Greenway Rd PO Box 3425 Boone, NC 28607 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Website https://envirovationconsulting.com/ https://enviro	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
719-A Greenway Rd PO Box 3425 Boone, NC 28607 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Website https://envirovationconsulting.com/ esting and Monitoring <a href="Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: <a href=" mailto:united-statistics-statist-statistics-statist-statist-statist-statist-statist-statist-statist-statist-statist-statist-statist-statist-statist-statist-stati<="" td=""><td>No No No No</td><td>Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:</td><td>No No No No No</td>	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
719-A Greenway Rd PO Box 3425 Boone, NC 28607 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Website https://envirovationconsulting.com/ https://enviro	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
719-A Greenway Rd PO Box 3425 Boone, NC 28607 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Yes Yes	Website https://envirovationconsulting.com/ https://enviro	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
719-A Greenway Rd PO Box 3425 Boone, NC 28607 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No Yes Yes Yes	Website https://envirovationconsulting.com/ esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Mo	untains)		
Company		Listing Submitted		Area of state conducts work	
Evo Corporation		Phone (336) 725-5844		Coastal (East of I-95): Yes	
1703 Vargrave Street		Fax		Central (West of I-95 and East of I-77): Yes	
Winston-Salem, NC 27107	,	Website www.evocorp.net		Mountains (West of I-77): Yes	
00000				HOT Farriagness to Complete Constructions	
		sting and Monitoring	NI-	UST Equipment Service Contractors	NI-
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	Yes .
Er	nvironmen	tal Service Firms		Other: Vacuum Truck S	Services
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other: Transportation S	Services		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	7/29/2020	Area of state conducts work	
Excel Environmental Associates, PLLC		Phone (704) 853-0800		Coastal (East of I-95): Yes	
625 Huntsman Court		Fax (704) 853-3949		Central (West of I-95 and East of I-77): Yes	
Gastonia, NC 28054		(, , , , , , , , , , , , , , , , , , ,		Mountains (West of I-77): Yes	
	1	Website <u>www.excelengr.com</u>		Mountains (West of 1-77). Tes	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Fr	vironmen	tal Service Firms		Other:	
_ -					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
		UST Compliance Consultants: UST Equipment Verification:	<u>Yes</u> No		
Emergency Cleanup - Spill/Release:	No <u>Yes</u>				
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No <u>Yes</u>	UST Equipment Verification:	No		
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No <u>Yes</u> <u>Yes</u>	UST Equipment Verification: Waste Disposal and Treatment:	No		

	U	IST Service Prov	∕ider List (Mou	ntains)		
Company			Listing Submitted	8/4/2020	Area of state conducts work	
Fourstar Petroleum	F	Phone (540) 563-1022			Coastal (East of I-95): Yes	
1119 Beaumont Rd.		Fax (540) 362-1802			Central (West of I-95 and East of I-77): Yes	
Roanoke, VA 24019	We	ebsite www.fourstarpetro	o.com		Mountains (West of I-77): Yes	
Comm		•			LICT Equipment Comics Contractors	
		ng and Monitoring	t On analyllity Charaly	NI-	UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment	The state of the s	No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:		Statistical Iventory Reconcilia		No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:		Spill Prevention Equipment Te	esting:	No	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		Tank Tightness Testing:		No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:		UST Internal Inspections (Inte		No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:		UST Internal Lining Inspection	NS:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:		Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmental	Service Firms			Other: Wayne Dispensers and Verifo	one POS
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants	:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatmen	nt:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	1/1/2022	Area of state conducts work	
Galloway	F	Phone (303) 770-8884			Coastal (East of I-95): Yes	
6162 South Willow Drive		Fax (303) 770-3636			Central (West of I-95 and East of I-77): Yes	
Suite 320		(111)				
Greenwood Village, CO 80111					Mountains (Most of L77): Voc	
	We	ebsite www.Gallowayus.o	<u>com</u>		Mountains (West of I-77): Yes	
Comp		ebsite www.Gallowayus.ong and Monitoring	<u>com</u>		Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Comp Automatic Line Leak Detector Testing:	oliance Testir	<u> </u>		No		No
	oliance Testir	ng and Monitoring	t Operability Check:	No No	UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No No	ng and Monitoring Overfill Prevention Equipment	t Operability Check: tion Services:		UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Automatic Line Leak Detector Testing: Containment Sump Testing:	No No No <u>Yes</u>	ng and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliar	t Operability Check: tion Services:	No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No Yes No	ng and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Te	t Operability Check: tion Services: esting:	No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No <u>Yes</u> No No	ng and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Te Tank Tightness Testing:	t Operability Check: tion Services: esting: egrity Assessments): ns:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No Yes No No No	ng and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Inte	t Operability Check: tion Services: esting: egrity Assessments):	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No Yes No No No	ng and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliar Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Inte	t Operability Check: tion Services: esting: egrity Assessments): ns:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes No	ng and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliar Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Inte	t Operability Check: tion Services: esting: egrity Assessments): ns:	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes No	ng and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Inte UST Internal Lining Inspection Other:	t Operability Check: tion Services: esting: egrity Assessments): ns: UST/AST System	No No No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes No	ng and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliar Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Inte UST Internal Lining Inspectior Other: Service Firms	t Operability Check: tion Services: esting: egrity Assessments): ns: UST/AST System	No No No No No Design	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	ng and Monitoring Overfill Prevention Equipment Statistical Iventory Reconcilian Spill Prevention Equipment To Tank Tightness Testing: UST Internal Inspections (Inte UST Internal Lining Inspection Other: Service Firms UST Compliance Consultants	t Operability Check: tion Services: esting: egrity Assessments): ns: UST/AST System	No No No No No Design	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No Yes No	ng and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Inte UST Internal Lining Inspection Other: Service Firms UST Compliance Consultants UST Equipment Verification:	t Operability Check: tion Services: esting: egrity Assessments): ns: UST/AST System	No No No No Design Yes No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No No Yes No	ng and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Inte UST Internal Lining Inspection Other: Service Firms UST Compliance Consultants UST Equipment Verification: Waste Disposal and Treatmen	t Operability Check: tion Services: esting: egrity Assessments): ns: UST/AST System	No No No No Design Yes No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

	l	JST Service Provider List (Mou	untains)		
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Geo-Hydro Engineers, Inc.		Phone (704) 837-7174		Coastal (East of I-95): Yes	
2748 Interstate Street		Fax		Central (West of I-95 and East of I-77): Yes	
Suite A				Mountains (West of I-77): Yes	
Charlotte, NC 28208	W	ebsite <u>www.geohydro.com</u>		mountains (west of 177). Tes	
Comp	pliance Testi	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı <u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/3/2022	Area of state conducts work	
Geological Resources, Inc.		Phone (704) 845-4010		Coastal (East of I-95): Yes	
3502 Hayes Road		Fax (704) 845-4012		Central (West of I-95 and East of I-77): Yes	
Monroe, NC 28112		(101) 010		Mountains (West of I-77): Yes	
	W	ebsite grienv.com		modificants (West of 1-77). Tes	
Comp	pliance Testi	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
				UST Equipment Repair:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	OOT Equipment (Cepail:	
	No No	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No	UST System Installation - Complete Systems:	No
Corrosion Protection System Testing:					No No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:		UST System Installation - Complete Systems:	
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No	UST Internal Lining Inspections:		UST System Installation - Complete Systems: UST Piping/Sump Installation:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No	UST Internal Lining Inspections: Other:		UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No nvironmenta	UST Internal Lining Inspections: Other: Il Service Firms	No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No No No nvironmenta Yes Yes	UST Internal Lining Inspections: Other: Il Service Firms UST Compliance Consultants:	No No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No nvironmenta Yes Yes	UST Internal Lining Inspections: Other: Il Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No	UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No	UST Internal Lining Inspections:		UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No

		JST Service Provider List (Mou	ıntains)		
Company		Listing Submitted	11/18/2020	Area of state conducts work	
Groundwater Management Associates, Inc.		Phone (252) 758-3310		Coastal (East of I-95): Yes	
4300 Sapphire Court		Fax		Central (West of I-95 and East of I-77): Yes	
Suite 100				Mountains (West of I-77): Yes	
Greenville, NC 27834	V	Vebsite www.gma-nc.com		modificants (West of 177). Tes	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/25/2022	Area of state conducts work	
HARCO Services LLC		Phone (770) 917-8846		Coastal (East of I-95): Yes	
PO Box 2347		Fax (770) 917-0921		Central (West of I-95 and East of I-77): Yes	
Kennesaw, GA 30156		144 (119) 611 6621			
	V	Vebsite www.harcoservices.com		Mountains (West of I-77): Yes	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
				HOTE I ALL A HALL ON	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No	Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No	UST Equipment Installation - Other: UST Equipment Repair:	No No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No	UST Equipment Repair: UST System Installation - Complete Systems:	No <u>Yes</u>
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No <u>Yes</u> <u>Yes</u>
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No <u>Yes</u> <u>Yes</u>
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No nvironment	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No <u>Yes</u> <u>Yes</u>
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No No No No nvironmenta No No	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No <u>Yes</u> <u>Yes</u>
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No nvironmenta No No	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No <u>Yes</u> <u>Yes</u>
Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No	UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No	UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No <u>Yes</u> <u>Yes</u>

		UST Service Provider List (Mo	untains)		
Company		Listing Submitted		Area of state conducts work	
Highlands Environmental Solutions, Inc.		Phone (919) 848-3155		Coastal (East of I-95): Yes	
8410-d Falls of Neuse		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27615				Mountains (West of I-77): Yes	
		Website www.HESfast.com			
Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/18/2020	Area of state conducts work	
INDUSTRY STANDARD CORRSION CONTROL	- LLC	Phone (252) 229-0485		Coastal (East of I-95): Yes	
				· · · · · · · · · · · · · · · · · · ·	
400 HARBOR DRIVE		,		Central (West of I-95 and Fast of I-77): Yes	
400 HARBOR DRIVE NEW BERN, NC 28560		Fax (704) 972-0300		Central (West of I-95 and East of I-77): Yes	
		,		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
NEW BERN, NC 28560	oliance Te	Fax (704) 972-0300			
NEW BERN, NC 28560	oliance Te No	Fax (704) 972-0300 Website WWW.ISCC.TECH	No	Mountains (West of I-77): Yes	No
NEW BERN, NC 28560		Fax (704) 972-0300 Website WWW.ISCC.TECH esting and Monitoring	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
NEW BERN, NC 28560 Compa	No	Fax (704) 972-0300 Website WWW.ISCC.TECH esting and Monitoring Overfill Prevention Equipment Operability Check:		Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
NEW BERN, NC 28560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Fax (704) 972-0300 Website WWW.ISCC.TECH esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
NEW BERN, NC 28560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No <u>Yes</u>	Fax (704) 972-0300 Website WWW.ISCC.TECH esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
NEW BERN, NC 28560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No <u>Yes</u> <u>Yes</u>	Fax (704) 972-0300 Website WWW.ISCC.TECH esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
NEW BERN, NC 28560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No Yes Yes Yes	Fax (704) 972-0300 Website WWW.ISCC.TECH esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
NEW BERN, NC 28560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No Yes Yes Yes No	Fax (704) 972-0300 Website WWW.ISCC.TECH Esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
NEW BERN, NC 28560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes Yes No No	Fax (704) 972-0300 Website WWW.ISCC.TECH Esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
NEW BERN, NC 28560 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes Yes No No	Fax (704) 972-0300 Website WWW.ISCC.TECH esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
NEW BERN, NC 28560 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er	No No Yes Yes Yes No No No No	Fax (704) 972-0300 Website WWW.ISCC.TECH esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
NEW BERN, NC 28560 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No No Yes Yes Yes No	Fax (704) 972-0300 Website WWW.ISCC.TECH Esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants:	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Compart Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No Yes Yes Yes No	Fax (704) 972-0300 Website WWW.ISCC.TECH esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Other: Other: Other Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
NEW BERN, NC 28560 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No No Yes Yes Yes No	Fax (704) 972-0300 Website WWW.ISCC.TECH esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

JAD Associates, Inc. 92 Moore Road 92 Moore Road 92 Moore Road 92 Moore Road 93 More Road 94 More Road 94 More Road 95 More Road 96 More Road 96 More Road 97 More Road 98 More Road 98 More Road 98 More Road 99 More Road 99 More Road 99 More Road 90 Mor			UST Service Provider List (Mo	ountains)	
Part	Company		,		Area of state conducts work
Avon Lake, Ohio 44012 Vebsite Www.jdgle.com	JGD Associates, Inc.		Phone 4409336825		Coastal (East of I-95): Yes
Compilance Testing and Monitoring No Overfill Provention Equipment Operability Check: No Dispensed Monitoring No Overfill Provention Equipment Operability Check: No Dispensed Monitoring No Statistical Intenderly Reconciliation Services: No Dispensed Monitoring No Overfill Provention Equipment Testing: No Spill Reconstruction System Repairs: No Tark Tightness Testing: No Tark Tightness Testing: No Other: Tark Tightness Testing: No UST Operations Testing: No Other: Tark Tightness Tes			Fax		Central (West of I-95 and East of I-77): Yes
Compliance Testing and Monitoring UST Equipment Service Contractors No	Avon Lake, Ohio 44012				Mountains (West of I-77): Yes
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Chack: No Ostationment Sump Testing: No Statistical I ventrory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No UST Equipment Installation Servicing: No UST Internal Line I begin Experts: No UST Internal Line I begin Experts: No UST Equipment Repairs: No UST Internal Line I begin Experts: No UST Internal Line I begin Experts: No UST Equipment Repairs: No UST Equipment Repairs: No UST System Installation - Compiles Systems: No UST System Installation - Compiles Systems: No UST System Installation - Compiles Systems: No UST System Installation: No UST System Installation: No UST System Installation: UST System Installation: No UST System In			Website www.jgdpe.com		,
Containment Sump Teating: Ormosion Protection Design Experts: No Spill Prevention Equipment Installation Servicing: No Spill Bucket Installation Repair: No Spill Bucket Installation Repair: No UST Internal Inspections: No UST Organian Services: No UST Compliance Consultants: No UST Compliance Consultants: No UST Compliance Consultants: No UST Compliance Consultants: No UST Compliance Inspires (Geologist Stat Checks: No UST Equipment Verification: No Ustream Inspires (Geologist Stat Checks: No UST Equipment Verification: No Ustream Inspires (Geologist Stat Checks: No UST Equipment Network Company Company Company Company Company Compliance Services Phone (770) 447-4555 Suite 130 Peachtree Corners, GA 30092 Website Compliance Testing and Monitoring Website Compliance Testing and Monitoring No Spill Prevention Equipment Operability Check: No UST Equipment Installation Servicing: No Spill Prevention Equipment Operability Check: No UST Equipment Installation Complete Systems: No UST System Repair: No UST Equipment Installation Complete Systems: No UST Equipment Installation Complete Systems: No UST System Repair: No UST Equipment Installation Complete Systems: No UST Eq	Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors
Corresion Protection Design Experts: No Spill Prevention Equipment Testing: No UST Equipment Installation Repair: No Corresion Protection System Repairs: No UST Internal Inspections: No UST Equipment Repair: No UST System Installation - Correlate Spatement Service Firms Emergency Clearup - Spill/Release: No UST Compliance Consultants: No UST Equipment Repair: UST installation - Correlate Spatement Service Firms Emergency Clearup - Spill/Release: No UST Compliance Consultants: No UST Equipment Verification: No Other: UST installation - Compliance Spill Release: No UST Equipment Verification: No Other: UST Installation - Compliance Spill Release: No UST Equipment Verification: No Other: UST Installation - Compliance Spill Release: No UST Equipment Verification: No Other: UST Installation - Compliance Spill Release: No UST Equipment Verification: No Other: UST Installation - Compliance Spill Release: No Other: UST Installation - Compliance Spill Re	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No
Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Operability Check: No UST Compliance Consultants: No UST Operability Check: No UST Equipment Verification: No Cher: UST Operability Check: No UST Installation - Operability Check: No UST Operability Check: No UST Installation - Operability Check: No UST Op	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No
Corresion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST System Installation Complete Systems: No Leak Detection Monitoring Services: No Other: No UST System Installation: No Other: UST System Removal: No Other: UST installation: No Other: UST System Removal: No Other: UST installation:	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST system Installation - Complete Systems: No UST operability Check: No UST System Installation: No UST System Installation: No UST System Removal: No UST System Removal: No UST System Removal: No UST System Removal: UST Piping/Sump Installation: No UST Graphiance Consultants: No UST Compliance Consultants: No UST Compliance Consultants: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No UST Compliance Consultants: No UST Equipment Installation Repair: No UST Equipment Installation Complete Systems: No UST Equipment Repairs: No UST Equipment Installation Complete Systems: No UST Equipment Installation Complete Systems: No UST Equipment Repairs: No UST	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No
Leak Detection Monitoring Services: No Other: Line Tightness Testing: No UST Compliance Consultants: No Cenvironmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No UST Compliance Consultants: No Cenvironmental Engineer/Geologist Sol and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other: UST installation drawings UST Compliance Consultants: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No Other: UST installation drawings UST System Removal: UST installation drawings UST System Removal: UST installation drawings UST System Removal: UST installation drawings UST Equipment Verification: No UST Equipment Service Firms UST Equipment Service Contractors No UST Equipment Installation Service: No Leak Detection Equipment Operability Check: Yes UST Equipment Installation Service: No Corrosion Protection System Repairs: No Corrosion Protection System Repairs: No UST Equipment Installation Service: No UST Equipment Operability Check: Yes UST System Removal: No UST Equipment Installation - Other: No UST Equipment Deposition Services: No UST Equipment Operability Check: Yes UST System Removal: No UST System Removal: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST System Removal: No UST System Rem	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No
Line Tightness Testing: No UST System Removal: No Other: Other: UST installation drawings Company	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Compliance Consultants: No UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Ust Equipment Verification: No Ust Equipment Installation Services: No Ust Equipment Installation Servicies: No Ust Equipment Installation Complete System setting: No Ust Internal Inspections (Integrity Assessments): No Ust Equipment Installation Other: No Ust Equipment Repair: No Ust Equipment Installation Other: No Ust System Removal: No Ust Equipment Installation Other: No Ust System Installation Other: No Ust System Installation Other: Engineering-Design Services Emergency Cleanup - Spill/Release: No Ust Equipment Verification: Yes Environmental Engineer/Geologist - Stot Checks: No Ust Equipment Verification: Yes Environmental Engineer/Geologist - Stot Checks: No Ust Equipment Verification: No Ust Engineering-Design Services	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Waste Disposal and Treatment: No Other: Company	Line Tightness Testing:	No			UST System Removal: No
Environmental Engineer/Geologist - Site Checks: No Waste Disposal and Treatment: No Other: Oliand Solvent Recycling: No Other: Soil and Water Testing Lab: No Other: Company	Eı	nvironme	ntal Service Firms		Other: UST installation drawings
Environmental Engineer/Geologist - Site Checks: No Waste Disposal and Treatment: No Other: Oliand Solvent Recycling: No Other: Soil and Water Testing Lab: No Other: Company	Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No	
Environmental Engineer/Geologist Soil and GW Cleanu No Other: No Overfill Prevention Equipment Operability Check: Yes Ocrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Other: No O					
Oil and Solvent Recycling: Soil and Water Testing Lab: No Other: Soil and Water Testing Lab: No Other: Soil and Water Testing Lab: No Other: Soil and Water Testing Lab: No Other: Soil and Water Testing Lab: Phone (770) 447-4555 SOR Research Ct. Suite 130 Peachtree Corners, GA 30092 Website Compliance Testing and Monitoring Website Website Website Website UST Equipment Service Contractors Contrail (West of I-97): Yes Mountains (West of I-77): Yes Mountains (West of I-77): Yes Containment Sump Testing: No Overfill Prevention Equipment Operability Check: Yes Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation Servicing: No UST Equipment Repairs: No UST Equipment Repairs: No UST Equipment Negation: No UST Equipment Negation (Integrity Assessments): No UST Equipment Negation (Ontegrity Assessments): No UST Equipment Repairs: No UST Equipment Negation (No UST Equipment Negation): No UST Equipment Negation (No UST Equipment Negation): No UST Equipment Negation: No UST Equipment					
Company Listing Submitted 1/5/2022 Area of state conducts work				-	
Listing Submitted 1/5/2022 Area of state conducts work	• •	No			
Johnson, Spellman & Associates, Inc. Phone (770) 447-4555 Solite 130 Peachtree Corners, GA 30092 Website	Company		Listing Submitte	d 1/5/2022	Area of state conducts work
350 Research Ct. Suite 130 Peachtree Corners, GA 30092 Website Fax Website					Coastal (East of I-95): Yes
Peachtree Corners, GA 30092 **Website** **Compliance Testing and Monitoring** Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: **Yes** Automatic Line Leak Detector Testing: No Statistical Iventory Reconciliation Services: No Ocorrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No UST Equipment Installation Servicing: No UST Equipment Installation Repair: No UST Equipment Installation Papair: No UST Equipment Repair: No UST System Installation - Other: Engineering- Design Services UST Piping/Sump Installation: No UST System Removal: No UST System Removal: No UST System Removal: No UST System Removal: Engineering-Design Services Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Other: Engineering-Design Services	=		, ,		
Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: Ocortainment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection Design Experts: No UST Equipment Installation Servicing: No UST Equipment Installation Servicing: No UST Equipment Installation Servicing: No UST Equipment Installation Operation: No UST Eq	Suite 130		Гах		
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: Yes Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Servicing: No Corrosion Protection Design Experts: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST System Repairs: No Other: Engineering- Design Services Environmental Service Firms Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Yes Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Engineering-Design Services In Other: Engineering-Design Services Environmental Engineer/Geologist Soil and GW Cleanu No Other: Engineering-Design Services Dispenser Meter Repair/Calibration: No UST Equipment Installation Servicing: No UST Equipment Installation Repair: No UST Equipment Installation Papair: No UST Equipment Installation Other: No UST Equipment Installation Other: No UST Equipment Installation Papair: No UST Equipment Installation Other: No UST Equipment Installation Papair: No UST Equipm	Peachtree Corners, GA 30092		Website		Mountains (West of I-77): Yes
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: No UST System Remov	Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation Repair: No Leak Detection System Testing: No UST Internal Inspections (Integrity Assessments): No Leak Detection Equipment Operability Check: Yes UST Internal Lining Inspections: No Other: Engineering- Design Services Line Tightness Testing: No UST Compliance Consultants: Yes Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Environmental Engineer/Geologist Soil and GW Cleanu No Other: Engineering-Design Services No Other: Engineering-Design Services In Corrosion Protection Design Experts: No UST Equipment Installation Servicing: No UST Equipment Installation Repair: No UST Equipment Installation	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration: No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST Equipment Repair: No Leak Detection Equipment Operability Check: Yes UST Internal Lining Inspections: No UST System Installation - Complete Systems: No Leak Detection Monitoring Services: No Other: Engineering- Design Services No UST System Installation - Complete Systems: No UST System Removal: UST System Removal: No Other: Services Service Firms	Containment Sump Testing:	No			
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No Leak Detection Equipment Operability Check: Yes UST Internal Lining Inspections: No Other: Engineering- Design Services UST Equipment Repair: UST Equipment Repair: UST Piping/Sump Installation: UST System Removal: Other: Engineering- Design Services Other: Engineering- Design Services	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No
Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: No Line Tightness Testing: No Conductor Firms Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu No Other: Engineering-Design Services No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No UST System Removal: No UST System Installation - Complete Systems: No UST System Installati	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No
Leak Detection Monitoring Services: Line Tightness Testing: No Environmental Service Firms	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No
Line Tightness Testing: Environmental Service Firms Service Firms	Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No
Line Tightness Testing: Environmental Service Firms Service Firms	Leak Detection Monitoring Services:	No	Other: Engineering- Design	Services	UST Piping/Sump Installation: No
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No UST Compliance Consultants: Yes Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes No Engineering-Design Services			-		
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No UST Compliance Consultants: Yes Yes No UST Equipment Verification: Yes No Engineering-Design Services	E	nvironme	ntal Service Firms		Other: Engineering-Design Services
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: Engineering-Design Services	Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes	
Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other: Engineering-Design Services					
Oil and Solvent Recycling: No Other: Engineering-Design Services					
		No	3 3 3 3		

		UST Service Provider List (Mo	untains)		
Company		Listing Submitted	12/20/2022	Area of state conducts work	
Jones Covey Group		Phone (888) 972-7581		Coastal (East of I-95): Yes	
9595 Lucas Ranch Rd STE 100		Fax (909) 484-0300		Central (West of I-95 and East of I-77): Yes	
Rancho Cucamonga, CA 91730				Mountains (West of I-77): Yes	
		Website			
Comp	pliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
E	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/27/2020	Area of state conducts work	
Labrador Environmental Consultants, P.C. (ea	stern	Phone (252) 809-9130		Coastal (East of I-95): Yes	
1450 Johnson Drive					
		Fax		Central (West of I-95 and East of I-77): Yes	
Williamston, NC 27892					
		Fax Website		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Williamston, NC 27892	oliance Te				
Williamston, NC 27892	pliance Te	Website	No	Mountains (West of I-77): Yes	
Williamston, NC 27892		Website esting and Monitoring	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Williamston, NC 27892 Comp Automatic Line Leak Detector Testing:	No	Website esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:		Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Williamston, NC 27892 Comparing Line Leak Detector Testing: Containment Sump Testing:	No No	Website esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No
Williamston, NC 27892 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No	Website Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Williamston, NC 27892 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No	Website esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Williamston, NC 27892 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Website Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Williamston, NC 27892 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Website Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Williamston, NC 27892 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Website Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Williamston, NC 27892 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Website esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Williamston, NC 27892 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No	Website Sesting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Williamston, NC 27892 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	No Vo	Website Stating and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants:	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Williamston, NC 27892 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanur Oil and Solvent Recycling:	No Vo No Tronmer	Website Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No No Ves	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Williamston, NC 27892 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	No No No No No No No No No Vo rvironmer Yes Yes Yes	Website esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No No Ves	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

Law Petroleum, Inc. 1025 Arlington Church Road Fax (704) 573-35355 Compliance Testing and Monitoring Lustrate Line Leak Datector Testing: Yes Overfull Prevention Equipment Operability Check: Yes Contrainent Sump Testing: Yes Substituted Inventor Equipment Operability Check: Yes Corrosion Protection System Repairs: Corrosion Protection System Repairs: Corrosion Protection System Repairs: Yes Corrosion Protection System Testing: Yes Corrosion System Repairs: Yes UST Instemal Inspections (Integrity Assessments): Yes Corrosion System Repairs: Corrosion System Repairs: Yes Corrosion System Repairs: Corrosion System Repairs: Yes Corrosion System Repairs: Corrosion System Repairs: Corrosion System Repairs: Corrosion System Repairs: Yes Corrosion System Repairs: No Corrosion Protection System Repairs: Corrosion Protection System Repairs: Corrosion Protection System Repairs: Corrosion Protection Design Experts: No Corrosion Protection Design Experts: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Cor		l	JST Service Provider List (Mou	ntains)		
Fax (704) 573-3535 Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Ye	Company		Listing Submitted	8/18/2020	Area of state conducts work	
Website Wountains (West of 1-77): Yes	Law Petroleum, Inc.		Phone (704) 573-3535		Coastal (East of I-95): Yes	
Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Ves Covrill Prevention Equipment Operability Check: Ves Covrill Prevention Equipment Operability Check: Ves Covrill Prevention Equipment Operability Check: Ves Statistical Neuropy Recordination Services: No Spill Prevention Equipment Testing: Ves Spill Bucket Installation Servicing: Ves Obtroit Testing: Ves UST Internal Inspections: Ves UST Equipment Installation Complete System Repairs: Ves UST Internal Inspections: Ves UST Internal Inspections: Ves UST System Installation Complete System: Ves UST System Installation: Leak Detection System Repairs: Ves UST System Installation: Leak Detection Equipment Operability Check: Ves UST Internal Inspections: Ves UST System Installation: Leak Detection Installation: Leak Detection Equipment Operability Check: Ves UST System Installation: Leak Detection Equipment Operability Check: Ves UST System Installation: Leak Detection Equipment Operability Check: Ves UST System Installation: Leak Detection Equipment Operability Check: Ves UST System Installation: Leak Detection Equipment Operability Check: Leak Detection Equipment Operability Check: Ves UST System Removal: Other: Emergency Cleanup- Spill/Release: Emironomental Engineer/Geologist Sol and GW Cleanu On Wo Waste Disposal and Treatment: No Other: Compliance Testing No Other: Listing Submitted 8/10/2021 Area of state conducts work Constal (East of 1-95): No Central (West of 1-95 and East of 1-77): Yes Mountains (West of 1-77): Yes Website marriandslaplo.com Website marriandslaplo.com UST Equipment Service Contractors Automatic Line Leak Detector Testing No Other: Compliance Testing No Statistical Neuropy Recordination Services: No Spill Bucket Installation Repair: No Central (West of 1-95 and East of 1-77): Yes Mountains (West of 1-77): Yes Mountains (Wes	11025 Arlington Church Road		Fax (704) 573-3535		Central (West of I-95 and East of I-77): Yes	
Compliance Testing and Monitoring Automatic Line Leak Detector Testing: Yes Corrosion Protection Design Experts: No Spill Prevention Equipment Operability Check: Yes Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Yes Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Yes Corrosion Protection System Testing: Yes Corrosion Protection System Testing: Yes Tank Trightness Testing: Yes UST Internal Inspections (integrity Assessments): Yes UST Equipment Installation Chen: Yes UST Equipment Repairs: Yes UST Equipment Repairs: Yes UST System Installation - Chen: UST System Installation - Chen; Yes UST System Removal: UST System Installation Chen; UST System Installation Chen; UST System Installation Chen; UST System Installation Chen; UST System Inst	Charlotte, NC 28227		Walt alte		Mountains (West of I-77): Yes	
Automatic Line Lank Defeator Testing: Yas Overfill Prevention Equipment Operability Check: Yas Octrainment Sump Testing: Yas Statistical Ventrory Recorditation Services: No Spill Prevention Equipment Testing: Yas Statistical Ventrory Recorditation Services: No Spill Prevention Equipment Testing: Yas Statistical Ventrory Recorditation Services: No Spill Prevention Equipment Testing: Yas Statistical Ventrory Recorditation Services: No Spill Prevention Equipment Testing: Yas Statistical Ventrory Recorditation Services: Yas Octrosion Protection System Repairs: Yas Statistical Ventrory Recorditation Services: Yas Octrosion Protection System Repairs: Yas Statistical Ventrory Recorditation Services: Yas UST Equipment Installation - Other: Yas UST Equipment Repairs: Yas UST Equipment Repairs: Yas UST Equipment Repairs: Yas UST System Installation: Complete Systems: Yas UST System Installation: Complete Systems: Yas UST System Installation: Yas UST System Installation: Complete Systems: Yas UST System Installation: Yas UST S		V	vedsite			
Containment Sump Testing: Vas Statistical Nemotory Reconcilation Services: No Spill Prevention Equipment Testing: Vas Spill Bucket Installation Repair: Vas Spill Bucket Installation Repair: Vas UST Equipment Installation - Other: Vas UST Equipment Installation - Other: Vas UST Requipment Installation - Other: Vas UST Requipment Installation - Other: Vas UST Internal Inspections (Integrity Assessments): Vas UST Internal Inspections (Integrity Assessments): Vas UST Internal Inspections (Integrity Assessments): Vas UST Internal Inspections: Vas UST System Installation - Complete Systems: Vas UST System Installation: Vas UST Installation: Vas UST System Installation: Vas UST Other: UST Equipment Installation: Vas UST Installation: Vas U	Comp	oliance Tes	ting and Monitoring			
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Yes Corrosion Protection System Repairs: Yes Tank Tightness Testing: Yes UST Internal Inspections (integrity Assessments): Yes UST Equipment Repair: Yes UST System Installation - Other: Yes UST System Installation - Other	Automatic Line Leak Detector Testing:	<u>Yes</u>				No
Corrosion Protection System Repairs: Ves UST Internal Inspections: Ves UST Internal Inspections: Ves UST Equipment Installation - Other: Ves UST Equipment Repair: Ves UST Equipment Repair: Ves UST Equipment Repair: Ves UST System Installation: Ves UST System Removal: Ves UST System Removal: Ves UST System Installation: Ves UST System Removal: Ves UST System Repair: No Containment Sump Testing: No UST Equipment Versilitation Repair: No UST Equipment Repair: No UST Equipment Versilitation: No UST System Removal: Ves UST System Installation: Ves UST System Installation: Ves UST System Removal: Ves UST System Removal: Ves UST System Removal: Ves UST Equipment Versilitation System Testallation Complete Systems: No UST Equipment Installation: No UST System Installati	Containment Sump Testing:	<u>Yes</u>		No		<u>Yes</u>
Corrosion Protection System Tasting: Yes Leak Detection Equipment Operability Check: Yes Other: Ves Other: Set Other: Emergency Cleanup - Spill/Release: Fenvironmental Service Firms Emergency Cleanup - Spill/Release: Emironmental Engineer/Geologist - Site Checks: No Other: No Other: Wast Disposal and Treatment: No Other: Sol and Water Tasting Lab: No Other: Listing Submitted 8/10/2021 Area of state conducts work Constal (Rast of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes Website martinandslagle.com Corrosion Protection System Repairs: No Ostalistical ventory Recognizion (Integrity Assessments): No Ostalistical ventory Recognizion (Integrity Assessments): No Ostalistical ventory Recognizions: No Ostalistical ventory Recognizions: No Ostalistical ventory Recognizions: No Ostalistical ventory Recogniziation Services: No Ostalistical ventory Recognization Services:		No		<u>Yes</u>		<u>Yes</u>
Leak Detection Equipment Operability Check: Yas UST Internal Lining Inspections: Yas UST System Installation - Complete Systems: Yas UST Operation System Removal: UST Pyping/Sump Installation: Yas UST System Removal: UST Pyping/Sump Installation: Yas UST System Removal: UST System Remo						<u>Yes</u>
Leak Detection Monitoring Services: Yes Other: Line Tightness Testing: Yes Other: Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: Yes Yes Centronmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Spill and Water Testing Lab: No Other: Listing Submitted 8/10/2021 Area of state conducts work Company Listing Submitted 8/10/2021 Area of state conducts work Martin & Slagle GeoSciences, PA Phone 8286347741 Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Website martinandslagle.com Method Submitted Submi		<u>Yes</u>				
Environmental Engineer/Geologist Soli and GW Clean No UST Equipment Verification: Yes UST Compliance Consultants: Yes UST Compliance Consultants: Yes UST Compliance Consultants: Yes UST Compliance Consultants: Yes Consultants				<u>Yes</u>		
Emergency Cleanup - Spill/Release: Emergency Cleanup - Spill/Release: Emergency Cleanup - Spill/Release: Emergency Cleanup - Spill/Release: No UST Equipment Verification: Ves Emergency Cleanup - Spill/Release: No UST Equipment Verification: No Other: No Constal (East of 1-95): No Central (West of 1-95 and East of 1-77): Yes Mountains (West of 1-77): Yes Mountains	_		Other:			
Emergency Cleanup - Spill/Release: Yes Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Other:					•	<u>Yes</u>
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: Yes Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other: Soil and Water Testing Lab: No Company	Er	nvironment	al Service Firms		Other:	
Environmental Engineer/Geologist Soil and GW Cleanu No Other: No	Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Oil and Solvent Recycling: Soil and Water Testing Lab: No Company Listing Submitted 8/10/2021 Area of state conducts work Martin & Slagle GeoSciences, PA Phone 8286347741 Coastal (East of I-95): No 173 Sloan Road Franklin, NC 28734 Fax Website martinandslagle.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Corrosion Protection Design Experts: No Spill Prevention Equipment Operability Check: No Corrosion Protection System Repairs: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No UST Internal Inspections: No Leak Detector Testing: No UST Internal Inspections: No Corrosion Protection System Repairs: No UST Internal Inspections: No UST Equipment Repair: No UST Equipment Installation Repair: No Corrosion Protection System Testing: No UST Equipment Development Installation Repair: No UST Equipment Repair: No UST Equipment Installation - Other: No Corrosion Protection System Repairs: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST System Installation - Complete Systems: No UST Equipment Repair: No UST System Installation: No UST System Installation: No UST System Installation: No UST System Installation: No UST System Removal: No UST System Removal: No UST System Removal: No UST System Removal: No Cher: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Cher: Waste Disposal and Treatment: Yes Oil and Solvent Recycling: No Other:	Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Listing Submitted S/10/2021 Area of state conducts work	Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Martin & Slagle GeoSciences, PA Martin & Slagle GeoSciences, PA Phone 8286347741 Fax Website martinandslagle.com Website martinandslagle.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Bucket Installation Repair: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Operability Check: No UST Internal Lining Inspections (Integrity Assessments): No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Removal: No Other:	Oil and Solvent Recycling:	No	Other:			
Martin & Slagle GeoSciences, PA Phone 8286347741 Fax Website martinandslagle.com UST Equipmment Service Contractors Mountains (West of I-77): Yes Mountains (West of I-77): Yes Wester Mountains (West of I-77): Yes Wester Mountains (West of I-77): Yes Wester Repair/Calibration: Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Installation: No UST System Repair: No UST System Installation: No UST System Installation: No UST System Installation: No UST System Removal: No UST System	Soil and Water Testing Lab:	No				
Frax Website martinandslagle.com	Company		Listing Submitted	8/10/2021	Area of state conducts work	
Website martinandslagle.com Compliance Testing and Monitoring UST Equipment Service Contractors	Martin & Slagle GeoSciences, PA		Phone 8286347741		Coastal (East of I-95): No	
Website martinandslagle.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection Design Experts: No UST Equipment Installation Repair: No Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: Yes Oil and Solvent Recycling: No Other:	173 Sloan Road		Fax		Central (West of I-95 and East of I-77): Yes	
Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection Osystem Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation Servicing: No UST Equipment Installation Repair: No UST Equipment Installation Repair: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Repairs: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No UST System Removal: No UST System Removal: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Verification: No Other:	Franklin, NC 28734				Mountains (West of I-77): Yes	
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No Spill Prevention Equipment Testing: No Spill Brevention Equipment Testing: No Spill Bucket Installation Repair: No Spill Bucket Installation Repair: No UST Equipment Installation Other: No UST Equipment Installation Other: No UST Equipment Installation Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: No UST Sys		V	Vebsite martinandslagle.com			
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: No UST S	Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST Piping/Sump Installation: No UST System Removal: No UST	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No UST	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: No Other:	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST Piping/Sump Installation: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes Oil and Solvent Recycling: No Other:	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation: No UST System Removal:	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Line Tightness Testing: Environmental Service Firms	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Oil and Solvent Recycling: Other:	Leak Detection Monitoring Services:	No	Other:			No
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes Oil and Solvent Recycling: No Other:	Line Tightness Testing:	No				No
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes Oil and Solvent Recycling: No Other:	Er	nvironment	al Service Firms		Other:	
Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes Other:	Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Oil and Solvent Recycling: No Other:	Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
	Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Soil and Water Testing Lab: No	Oil and Solvent Recycling:	No	Other:			
						1

	l	JST Se	ervice Provider List (Mo	ountains)		
Company			Listing Submitte		Area of state conducts work	
Mid-Atlantic Associates, Inc.		Phone (9	919) 250-9918		Coastal (East of I-95): Yes	
409 Rogers View Ct		Fax (9	919) 250-9950		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27610	v	Vebsite w	vww.maaonline.com		Mountains (West of I-77): Yes	
	oliance Tes				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No		evention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No		Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No		ention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	_	tness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No		nal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No		nal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
Er	nvironment	al Service F	Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Comp	oliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes		oment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu			posal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitte	ed 12/30/2021	Area of state conducts work	
NCPCM		Phone (9	919) 782-4411		Coastal (East of I-95): Yes	
7300 glenwood ave.		Fax (9	919) 782-4414		Central (West of I-95 and East of I-77): Yes	
raleigh, NC 27612					Mountains (West of I-77): Yes	
	V	Vebsite <u>w</u>	vww.ncpcm.org		,	
Comp	oliance Tes	ting and Mo	onitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Pre	evention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iv	Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prever	ention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightr	tness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Interna	nal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No		nal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	No
Er	nvironment	al Service F	Firms		Other:	
		LIOT	oliance Consultants:	<u>Yes</u>		
Emergency Cleanup - Spill/Release:	No	UST Comp	oliance Consultants.	<u></u>		
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No		oment Verification:	No No		
	No	UST Equipr				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipr	oment Verification:	No No		
Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No No	UST Equipr Waste Disp	oment Verification: posal and Treatment:	No No		

		UST Service Provider List (Mo	untains)		
Company		Listing Submitted	7/30/2020	Area of state conducts work	
Nova Group GBC		Phone (704) 258-5196		Coastal (East of I-95): Yes	
442 South Main St		Fax		Central (West of I-95 and East of I-77): Yes	
Suite # 7 Davidson, NC 28036	,	Mahadia humadhaan an an an an an a		Mountains (West of I-77): Yes	
Davidson, 110 2000	١	Website https://www.novagroupgbc.com/		·	
Com	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: Environmental compliance ins	pections	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	invironment	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	u <u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other: due o	diligence		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	2/28/2022	Area of state conducts work	
Company Parliament Petroleum Services LLC		Phone (864) 871-8058	2/28/2022	Area of state conducts work Coastal (East of I-95): No	
Parliament Petroleum Services LLC 3277 Neely Ferry Rd			2/28/2022		
Parliament Petroleum Services LLC		Phone (864) 871-8058 Fax	2/28/2022	Coastal (East of I-95): No	
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360		Phone (864) 871-8058 Fax Nebsite Parliamentpetroleumservices.com	2/28/2022	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes	
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360		Phone (864) 871-8058 Fax	2/28/2022	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No	
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360		Phone (864) 871-8058 Fax Nebsite Parliamentpetroleumservices.com	2/28/2022 No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes	Yes
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360 Com	pliance Tes	Phone (864) 871-8058 Fax Website Parliamentpetroleumservices.com sting and Monitoring		Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	Yes Yes
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Tes	Phone (864) 871-8058 Fax Website Parliamentpetroleumservices.com sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Tes No No	Phone (864) 871-8058 Fax Website Parliamentpetroleumservices.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	<u>Yes</u>
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Tes No No No	Phone (864) 871-8058 Fax Website Parliamentpetroleumservices.com Iting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	pliance Tes No	Phone (864) 871-8058 Fax Website Parliamentpetroleumservices.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (864) 871-8058 Fax Website Parliamentpetroleumservices.com Iting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes Yes
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	pliance Tes No	Phone (864) 871-8058 Fax Website Parliamentpetroleumservices.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (864) 871-8058 Fax Website Parliamentpetroleumservices.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes Yes
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (864) 871-8058 Fax Website Parliamentpetroleumservices.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (864) 871-8058 Fax Website Parliamentpetroleumservices.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	No N	Phone (864) 871-8058 Fax Nebsite Parliamentpetroleumservices.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
Parliament Petroleum Services LLC 3277 Neely Ferry Rd Laurens, SC 29360 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (864) 871-8058 Fax Website Parliamentpetroleumservices.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes

	ι	JST Service Provider List (Mou	ıntains)		
Company		Listing Submitted	7/30/2020	Area of state conducts work	
Peak Hydrogeologic, PLLC		Phone (828) 817-5209		Coastal (East of I-95): No	
470 Hogback Mountain Road		Fax		Central (West of I-95 and East of I-77): Yes	
Tryon, NC 28782				Mountains (West of I-77): Yes	
	W	debsite www.peakhydrogeologic.com			
Com	pliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Company Petroleum Equipment and Service, Inc.		Listing Submitted Phone (704) 335-8801	12/30/2021	Area of state conducts work Coastal (East of I-95): No	
		Phone (704) 335-8801	12/30/2021	Coastal (East of I-95): No	
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949			12/30/2021	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
Petroleum Equipment and Service, Inc. 4125 Sinclair Street		Phone (704) 335-8801	12/30/2021	Coastal (East of I-95): No	
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037	W	Phone (704) 335-8801 Fax (704) 342-1672	12/30/2021	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes	
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037	W	Phone (704) 335-8801 Fax (704) 342-1672 /ebsite www.petroleumequipment.net	12/30/2021 Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	Yes
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 Com	W pliance Test	Phone (704) 335-8801 Fax (704) 342-1672 Vebsite www.petroleumequipment.net ing and Monitoring		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	Yes Yes
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 Com Automatic Line Leak Detector Testing:	W pliance Test Yes	Phone (704) 335-8801 Fax (704) 342-1672 /ebsite www.petroleumequipment.net ing and Monitoring Overfill Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	W pliance Test Yes Yes	Phone (704) 335-8801 Fax (704) 342-1672 Vebsite www.petroleumequipment.net ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	Yes No	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts:	W pliance Test Yes Yes No	Phone (704) 335-8801 Fax (704) 342-1672 Vebsite www.petroleumequipment.net ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes No Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Pliance Test Yes Yes No No No No Yes	Phone (704) 335-8801 Fax (704) 342-1672 Vebsite www.petroleumequipment.net ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Ves Yes Yes No No No No Yes Yes	Phone (704) 335-8801 Fax (704) 342-1672 Vebsite www.petroleumequipment.net ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Pliance Test Yes Yes No No No No Yes	Phone (704) 335-8801 Fax (704) 342-1672 Vebsite www.petroleumequipment.net ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 Comparison Comparison Comparison Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Western Properties With the Properties Williams	Phone (704) 335-8801 Fax (704) 342-1672 Vebsite www.petroleumequipment.net ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	Western Properties With the Properties Williams	Phone (704) 335-8801 Fax (704) 342-1672 Vebsite www.petroleumequipment.net ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Pliance Test Yes Yes No No No Yes Yes Yes Yes Yes Yes Novironmenta	Phone (704) 335-8801 Fax (704) 342-1672 Vebsite www.petroleumequipment.net ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	VI pliance Test Yes Yes No No No Yes Yes Yes Yes No No No No	Phone (704) 335-8801 Fax (704) 342-1672 Vebsite www.petroleumequipment.net ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	Yes No Yes Yes Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	VI pliance Test Yes Yes No No No Yes Yes Yes Yes No No No No	Phone (704) 335-8801 Fax (704) 342-1672 Vebsite www.petroleumequipment.net ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes Yes Yes	Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

		UST Service Provider List (M	lountains)		
Company		Listing Submit	tted 3/31/2022	Area of state conducts work	
Petroleum Tec		Phone (980) 781-1000		Coastal (East of I-95): Ye	es
5420 Powerhouse Ct		Fax		Central (West of I-95 and East of I-77): Ye	es
Concord, NC 28027				Mountains (West of I-77): Ye	es .
	\	Website www.petroleumtec.com		,	
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	6
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: Ta	ank Cleaning	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironment	tal Service Firms		Other: Tank	c Cleaning
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other: Ta	ank Cleaning		
Soil and Water Testing Lab:	No				
_					
Company		Listing Submit	tted 7/30/2020	Area of state conducts work	
		Phone (336) 310-4527	tted 7/30/2020	Area of state conducts work Coastal (East of I-95): Ye	es
Pilot Geological, PLLC 743 Park Lawn Court		Phone (336) 310-4527	tted 7/30/2020	Coastal (East of I-95): Ye	
Pilot Geological, PLLC 743 Park Lawn Court PO 128			tted 7/30/2020	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye	es
Pilot Geological, PLLC 743 Park Lawn Court	\	Phone (336) 310-4527	tted 7/30/2020	Coastal (East of I-95): Ye	es
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285		Phone (336) 310-4527 Fax (336) 310-4527	tted 7/30/2020	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye	es es
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285		Phone (336) 310-4527 Fax (336) 310-4527 Website www.pilotenviro.com	7/30/2020 No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye	es es
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Comp	oliance Tes	Phone (336) 310-4527 Fax (336) 310-4527 Website www.pilotenviro.com Sting and Monitoring		Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractors	es es
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Compa	oliance Tes No	Phone (336) 310-4527 Fax (336) 310-4527 Website www.pilotenviro.com Sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	es es No
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Compa Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (336) 310-4527 Fax (336) 310-4527 Website www.pilotenviro.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	es es No No
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (336) 310-4527 Fax (336) 310-4527 Website www.pilotenviro.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	es es No No
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Phone (336) 310-4527 Fax (336) 310-4527 Website www.pilotenviro.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No	Phone (336) 310-4527 Fax (336) 310-4527 Website www.pilotenviro.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	NO NO NO NO NO NO NO NO
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (336) 310-4527 Fax (336) 310-4527 Website www.pilotenviro.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	NO NO NO NO NO
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 310-4527 Fax (336) 310-4527 Website www.pilotenviro.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	NO NO NO NO NO NO NO NO
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 310-4527 Fax (336) 310-4527 Website www.pilotenviro.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	NO NO NO NO NO NO NO NO
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 310-4527 Fax (336) 310-4527 Website www.pilotenviro.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	NO NO NO NO NO NO NO NO
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Phone (336) 310-4527 Fax (336) 310-4527 Website www.pilotenviro.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	NO NO NO NO NO NO NO NO
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Vo No No Tyes Yes	Phone (336) 310-4527 Fax (336) 310-4527 Nebsite www.pilotenviro.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No Vo	Coastal (East of I-95): Ye Central (West of I-95 and East of I-77): Ye Mountains (West of I-77): Ye UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	NO NO NO NO NO NO NO NO

		UST S	Service Provider List (Mou	ntains)		
Company			Listing Submitted		Area of state conducts work	
Precision Tank Service		Phone	(704) 892-8600		Coastal (East of I-95): Yes	
737 Zimmer Road		Fax	(704) 892-8711		Central (West of I-95 and East of I-77): Yes	
Fort Mill , SC 29707					Mountains (West of I-77): Yes	
	V	Website	www.precisiontankservice.com		,	
Comp	pliance Tes	sting and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistic	al Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pre	evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tig	ghtness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Inte	ernal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Inte	ernal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Eı	nvironment	tal Servic	e Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Co	mpliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Eq	uipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	l No	Waste D	Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	2/24/2020	Area of state conducts work	
Company Professional Service Industries, Inc.		Phone	Listing Submitted (704) 598-2234	2/24/2020	Area of state conducts work Coastal (East of I-95): Yes	
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd.			(704) 598-2234	2/24/2020	Coastal (East of I-95): Yes	
Professional Service Industries, Inc.		Fax	(704) 598-2234 (704) 598-2236	2/24/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd.	V		(704) 598-2234	2/24/2020	Coastal (East of I-95): Yes	
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269	V pliance Tes	Fax Website	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building	2/24/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269		Fax Website sting and	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building	2/24/2020 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269	pliance Tes	Fax Website Sting and Overfill	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269 Comparison Line Leak Detector Testing:	pliance Tes	Fax Website sting and Overfill Statistic	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building Monitoring Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes No No	Fax Website Sting and Overfill Statistic Spill Pre	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Fax Website sting and Overfill Statistic Spill Pre Tank Tig	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Fax Website Sting and Overfill Statistic Spill Pre Tank Tig UST Inte	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Fax Website Sting and Overfill Statistic Spill Pre Tank Tig UST Inte	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Fax Website Sting and Overfill I Statistic Spill Pre Tank Tig UST Inte	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No	Fax Website Sting and Overfill Statistic Spill Pre Tank Tig UST Inte UST Inte Other:	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax Website sting and Overfill I Statistic Spill Pre Tank Tig UST Int UST Int Other:	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax Website sting and Overfill Statistic Spill Pre Tank Tig UST Inte UST Inte Other:	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Entergency Cleanup - Spill/Release:	No N	Fax Website sting and Overfill Statistic Spill Pre Tank Tig UST Inte UST Inte Other: tal Servic UST Co UST Eq	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Fax Website sting and Overfill Statistic Spill Pre Tank Tig UST Inte UST Inte Other: tal Servic UST Co UST Eq	(704) 598-2234 (704) 598-2236 http://www.intertek.com/building Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

	l	JST Service Provider List (Mou	ıntains)		
Company		Listing Submitted	1/3/2022	Area of state conducts work	
Pyramid Environmental & Engineering, PC		Phone (336) 335-3174		Coastal (East of I-95): Yes	
503 Industrial Avenue		Fax (336) 691-0648		Central (West of I-95 and East of I-77): Yes	
Greensboro, NC 27406				Mountains (West of I-77): Yes	
	V	Vebsite www.PyramidEnvironmental.com		, ,	
Comp	oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	9/14/2020	Area of state conducts work	
Schnabel Engineering Sourh, P.C.		Phone (910) 769-1621		Coastal (East of I-95): Yes	
244 Princess Street, Suite 205		Fax		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28401		Tun			
	V	Vebsite www.schnabel-eng.com		Mountains (West of I-77): Yes	
Comp	oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	<u>Yes</u>		
011 101 10 11					
Oil and Solvent Recycling:	No	Other:			
Oil and Solvent Recycling: Soil and Water Testing Lab:		Other:			

	ι	JST Service Provider List (Mou	ıntains)		
Company		Listing Submitted		Area of state conducts work	
Singleton Environmental, Inc.		Phone (828) 508-4510		Coastal (East of I-95): Yes	
PO Box 604		Fax		Central (West of I-95 and East of I-77): Yes	
Fletcher, NC 28732				Mountains (West of I-77): Yes	
	W	ebsite singletonenvironmental.com			
Comp	oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	12/30/2021	Area of state conducts work	
Superior Services		Phone (828) 698-6286		Coastal (East of I-95): Yes	
PO Box 982		Fax (828) 698-6294		Central (West of I-95 and East of I-77): Yes	
Hendersonville, NC		(020) 000 020 1			
	W	/ebsite <u>www.superiorservices.com</u>		Mountains (West of I-77): Yes	
Comp	oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: Repair and lining, AST Inspections, Repairs and	l Lining	UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

	UST	Service Provider List (Mou	ıntains)		
Company		Listing Submitted		Area of state conducts work	
Terraquest Environmental Consultants, P.C.	Phone	(919) 563-9091		Coastal (East of I-95): Yes	
100 E. Ruffin Street	Fax	(919) 563-9095		Central (West of I-95 and East of I-77): Yes	
Mebane, NC 27302				Mountains (West of I-77): Yes	
	Website	www.terraquestpc.com		,	
Complia	ance Testing and	d Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No Overfill	Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	•	revention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No Tank T	ightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing: N	No UST In	iternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check: N	No UST In	iternal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Envi	ironmental Servi	ce Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>res</u> UST C	ompliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>res</u> UST E	quipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu Y	<u>Yes</u> Waste	Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No Other:				
Soil and Water Testing Lab:	<u>′es</u>				
Company		Listing Submitted	3/26/2021	Area of state conducts work	
The Mannik & Smith Group, Inc.	Phone	(336) 302-9598		Coastal (East of I-95): Yes	
4501 New Bern Avenue	Fax			Central (West of I-95 and East of I-77): Yes	
C: 4 204244	гах				
Suite 130#214	Гах				
Raleigh, NC 27610	Website			Mountains (West of I-77): Yes	
Raleigh, NC 27610		www.MannikSmithGroup.com			
Raleigh, NC 27610 Complia	Website	www.MannikSmithGroup.com	No	Mountains (West of I-77): Yes	No
Raleigh, NC 27610 Complia Automatic Line Leak Detector Testing:	Website ance Testing and	www.MannikSmithGroup.com Monitoring	No No	Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Raleigh, NC 27610 Complia Automatic Line Leak Detector Testing: Containment Sump Testing: N	Website ance Testing and No Overfill No Statisti	www.MannikSmithGroup.com d Monitoring Prevention Equipment Operability Check:		Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Raleigh, NC 27610 Complia Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: N	Website ance Testing and No Overfill No Statisti No Spill Pr	www.MannikSmithGroup.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services:	No	Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Raleigh, NC 27610 Complia Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: N	Website ance Testing and No Overfill No Statisti No Spill Pr No Tank T	www.MannikSmithGroup.com d Monitoring I Prevention Equipment Operability Check: cal Iventory Reconciliation Services: revention Equipment Testing:	No No	Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Raleigh, NC 27610 Complia Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: N	Website ance Testing and No Overfill No Statisti No Spill Pr No Tank T No UST In	www.MannikSmithGroup.com d Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: revention Equipment Testing: rightness Testing:	No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Raleigh, NC 27610 Complia Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Website ance Testing and No Overfill No Statisti No Spill Pr No Tank T No UST In	www.MannikSmithGroup.com I Prevention Equipment Operability Check: cal Iventory Reconciliation Services: revention Equipment Testing: rightness Testing: iternal Inspections (Integrity Assessments): iternal Lining Inspections:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Raleigh, NC 27610 Complia Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: N	Website Ance Testing and No Overfill No Statisti No Spill Pr No Tank T No UST In No UST In	www.MannikSmithGroup.com I Prevention Equipment Operability Check: cal Iventory Reconciliation Services: revention Equipment Testing: rightness Testing: iternal Inspections (Integrity Assessments): iternal Lining Inspections:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Raleigh, NC 27610 Complia Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Website Ance Testing and No Overfill No Statisti No Spill Proceed to the control of the control	www.MannikSmithGroup.com d Monitoring I Prevention Equipment Operability Check: cal Iventory Reconciliation Services: revention Equipment Testing: rightness Testing: uternal Inspections (Integrity Assessments): uternal Lining Inspections:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Raleigh, NC 27610 Complia Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: N Envir	Website Ance Testing and No Overfill No Statisti No Spill Pro No Tank To No UST In No UST In No Other: No Other: No Otheri	www.MannikSmithGroup.com d Monitoring I Prevention Equipment Operability Check: cal Iventory Reconciliation Services: revention Equipment Testing: rightness Testing: uternal Inspections (Integrity Assessments): uternal Lining Inspections:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Raleigh, NC 27610 Complia Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	Website Ance Testing and No Overfill No Statisti No Spill Provided to the control of the contro	www.MannikSmithGroup.com d Monitoring I Prevention Equipment Operability Check: cal Iventory Reconciliation Services: revention Equipment Testing: Tightness Testing: sternal Inspections (Integrity Assessments): sternal Lining Inspections:	No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Raleigh, NC 27610 Complia Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: N Environmental Engineer/Geologist - Site Checks: Y	Website ance Testing and No Overfill No Statisti No Spill Pr No Tank T No UST In No UST In No Other: No Other: No UST In	www.MannikSmithGroup.com d Monitoring I Prevention Equipment Operability Check: cal Iventory Reconciliation Services: revention Equipment Testing: rightness Testing: uternal Inspections (Integrity Assessments): uternal Lining Inspections: ce Firms ompliance Consultants:	No No No No No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Raleigh, NC 27610 Complia Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: No Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	Website ance Testing and No Overfill No Statisti No Spill Pr No Tank T No UST In No UST In No Other: No Other: Ironmental Servi (es UST C	www.MannikSmithGroup.com d Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: revention Equipment Testing: rightness Testing: aternal Inspections (Integrity Assessments): aternal Lining Inspections: ce Firms ompliance Consultants: quipment Verification: Disposal and Treatment:	No No No No Yes No	Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

	l	JST Service Provider List (Mou	untains)		
Company		Listing Submitted	8/12/2020	Area of state conducts work	
TIMMONS GROUP		Phone (919) 866-4951		Coastal (East of I-95): Yes	
5410 TRINITY ROAD, SUITE 102		Fax		Central (West of I-95 and East of I-77): Yes	
RALEIGH, NC 27606	147	shaita huadhaan Garaga aand		Mountains (West of I-77): Yes	
	VV	ebsite http://www.timmons.com/			
Com	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironmenta	I Service Firms		Other: SYSTEM DESIGN SERVICES - UST ENGINE	ERING
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other: SYSTEM DESIGN SERVICES - UST ENGINE	ERING		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/13/2020	Area of state conducts work	
Company Unified Services of Texas		Listing Submitted Phone (817) 481-9510	8/13/2020		
• •		Phone (817) 481-9510	8/13/2020	Coastal (East of I-95): Yes	
Unified Services of Texas			8/13/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Unified Services of Texas 2110 Greenbriar dr.		Phone (817) 481-9510	8/13/2020	Coastal (East of I-95): Yes	
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092	w	Phone (817) 481-9510 Fax	8/13/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092	w	Phone (817) 481-9510 Fax ebsite ustfuel.com	8/13/2020 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092	W pliance Testi	Phone (817) 481-9510 Fax ebsite ustfuel.com ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No Yes
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092 Comparison	W pliance Testi <u>Yes</u>	Phone (817) 481-9510 Fax ebsite ustfuel.com ing and Monitoring Overfill Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	W pliance Testi Yes Yes	Phone (817) 481-9510 Fax ebsite ustfuel.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts:	W pliance Testi Yes Yes No	Phone (817) 481-9510 Fax ebsite ustfuel.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> Yes
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	W pliance Testi Yes Yes No No	Phone (817) 481-9510 Fax ebsite ustfuel.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Testi Yes Yes No No No	Phone (817) 481-9510 Fax ebsite ustfuel.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	W pliance Testi Yes Yes No No No No Yes	Phone (817) 481-9510 Fax ebsite ustfuel.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Pliance Testi Yes Yes No No No Yes Yes Yes Yes Yes	Phone (817) 481-9510 Fax ebsite ustfuel.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Pliance Testi Yes Yes No No No Yes Yes Yes Yes Yes	Phone (817) 481-9510 Fax ebsite ustfuel.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Testi Yes Yes No No No Yes Yes Yes Yes Yes Yes Norronmenta	Phone (817) 481-9510 Fax ebsite ustfuel.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	Pliance Testi Yes Yes No No No Yes Yes Yes Yes Yes Yes Noironmenta Yes Yes	Phone (817) 481-9510 Fax ebsite ustfuel.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Unified Services of Texas 2110 Greenbriar dr. Southlake, TX 76092 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Pliance Testi Yes Yes No No No Yes Yes Yes Yes Yes Yes nvironmenta	Phone (817) 481-9510 Fax ebsite ustfuel.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Il Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes Yes Yes Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

	U	ST Service Provider List (Mo	untains)		
Company		Listing Submitted	1/26/2022	Area of state conducts work	
UST Corrosion Management, Inc.	F	Phone (888) 822-2431		Coastal (East of I-95): Yes	
2764 Pleasant Rd #10714		Fax (803) 802-0561		Central (West of I-95 and East of I-77): Yes	
Fort Mill, SC 29708	We	bsite www.ustcorrosion.com		Mountains (West of I-77): Yes	
Com	pliance Testir	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:		Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:		Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:		Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:		UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No '	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	7/14/2022	Area of state conducts work	
VALLEY TANK TESTING		(2.12) 22.1		Coastal (East of I-95): Yes	
VALLET TANK TESTING	F	Phone (813) 671-9065		Coastal (Last of 1-33). 163	
451 APOLLO BEACH BOULEVARD	F	Phone (813) 671-9065 Fax (866) 328-9796		Central (West of I-95 and East of I-77): Yes	
		,			
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572	We	Fax (866) 328-9796		Central (West of I-95 and East of I-77): Yes	
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572	We	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM	Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572	We pliance Testin <u>Yes</u>	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM ag and Monitoring	<u>Yes</u> No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comp Automatic Line Leak Detector Testing:	We pliance Testir Yes Yes	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM ag and Monitoring Overfill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	Wepliance Testin Yes Yes No	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM ag and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparing Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	We pliance Testin Yes Yes No No	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM ag and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No <u>Yes</u>	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Wepliance Testin Yes Yes No No Yes	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM ag and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No <u>Yes</u> <u>Yes</u>	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison of the Comparison of t	We pliance Testin Yes Yes No No Yes Yes Yes	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM ag and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No <u>Yes</u> <u>Yes</u> No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison of the Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	We pliance Testin Yes Yes No No Yes Yes Yes	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM In g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We pliance Testin Yes Yes No No Yes Yes Yes Yes Yes Yes	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM In g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	We pliance Testir Yes Yes No No Yes Yes Yes Yes Yes Yes Yes Yes	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No <u>Yes</u> <u>Yes</u> No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison of Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	We pliance Testir Yes Yes No No Yes Yes Yes Yes Yes Yes You	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms	No Yes Yes No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison of the c	We pliance Testir Yes Yes No No Yes Yes Yes Yes Yes Yes You	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No Yes Yes No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
451 APOLLO BEACH BOULEVARD APOLLO BEACH, FL 33572 Comparison of Comparison of Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	We pliance Testir Yes Yes No No Yes Yes Yes Yes Yes No No No No No No No No No	Fax (866) 328-9796 bsite WWW.VALLEYTANK.COM ag and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No Yes Yes No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

	UST Service Provider List (Mou	ıntains)		
	Listing Submitted	1/31/2023	Area of state conducts work	
	Phone (205) 577-1035		Coastal (East of I-95): Yes	
	Fax		Central (West of I-95 and East of I-77): Yes	
V	Vebsite		mountaine (rest et 117).	
pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
No			UST System Removal:	<u>Yes</u>
nvironment	al Service Firms		Other:	
No	UST Compliance Consultants:	No		
No	UST Equipment Verification:	No		
J No	Waste Disposal and Treatment:	No		
No	Other:			
No				
	Listing Submitted	10/5/2021	Area of state conducts work	
	Listing Submitted Phone (919) 303-7374	10/5/2021	Area of state conducts work Coastal (East of I-95): Yes	
	Phone (919) 303-7374	10/5/2021	Coastal (East of I-95): Yes	
		10/5/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
V	Phone (919) 303-7374	10/5/2021	Coastal (East of I-95): Yes	
	Phone (919) 303-7374 Fax (919) 303-7399	10/5/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite	10/5/2021 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
pliance Tes	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite WWW.VITALFUELSYSTEMS.COM ting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No Yes
pliance Tes No	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite WWW.VITALFUELSYSTEMS.COM ting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
pliance Tes No No	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite WWW.VITALFUELSYSTEMS.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
pliance Tes No No No	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite WWW.VITALFUELSYSTEMS.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
pliance Tes No No No No	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite WWW.VITALFUELSYSTEMS.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
No No No No No No No No No	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite WWW.VITALFUELSYSTEMS.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
No No No No No No No No	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite WWW.VITALFUELSYSTEMS.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
No N	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite WWW.VITALFUELSYSTEMS.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
No N	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite WWW.VITALFUELSYSTEMS.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
No N	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite WWW.VITALFUELSYSTEMS.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
No N	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite WWW.VITALFUELSYSTEMS.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
No N	Phone (919) 303-7374 Fax (919) 303-7399 Vebsite WWW.VITALFUELSYSTEMS.COM ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
	No N	Phone (205) 577-1035 Fax Website pliance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: No Invironmental Service Firms No UST Compliance Consultants: No UST Equipment Verification: UNO Waste Disposal and Treatment: No Other:	Phone (205) 577-1035 Fax Website Pliance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No No Statistical Iventory Reconciliation Services: No No Spill Prevention Equipment Testing: No No Tank Tightness Testing: No No UST Internal Inspections (Integrity Assessments): No No UST Internal Lining Inspections: No No Other: No Invironmental Service Firms No UST Compliance Consultants: No No UST Equipment Verification: No No Other:	Listing Submitted 1/31/2023 Area of state conducts work Phone (205) 577-1035 Fax Website Website Diagram Monitoring No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: No UST Compliance Consultants: No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Installation - Other: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: Other: Other:

	US	ST Service Provider List	(Mou	ntains)		
Company		Listing Sul	bmitted	8/13/2020	Area of state conducts work	
WithersRavenel, Inc.	PI	none (919) 469-3340			Coastal (East of I-95): Yes	3
115 MacKenan Drive	Fax		Central (West of I-95 and East of I-77): Yes	;		
Cary, NC 27511	Website www.withersravenel.com			Mountains (West of I-77): Yes		
Comp	liance Testing	and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No C	verfill Prevention Equipment Operability Che	eck:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No S	tatistical Iventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No S	pill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No T	ank Tightness Testing:		No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No U	ST Internal Inspections (Integrity Assessmer	nts):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No U	ST Internal Lining Inspections:		No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No C	ther:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
Er	nvironmental S	Service Firms			Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u> U	ST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u> U	ST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes W	aste Disposal and Treatment:		<u>Yes</u>		
Oil and Solvent Recycling:	No C	ther:	Phase I	ESAs		
Soil and Water Testing Lab:	No					